FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7818 AND SIGNED WHEN RETURNED

DATE INSPECTED 6-25-65 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO
SIZE OF PIPE USED 6 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 120 NovTH of M 10
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN NAME OF CONTRACTOR A DIANA
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
CATACL AKS'
of the first of the control of the first of the control of the first section of the control of t
1/20
SIGNED Roy Kathon FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY
REMARKS

Nº 7818

PERMIT TO TAP SEWER

MASSILLON, OHIO, June 34
RECEIVED OF Hater 2600 FEE OF \$50
FOR WHICH PERMISSION IS GRANTED KITCHED 12 (dbc).
TO TAP Santay SEWER ON THE West
of Amilia 1)1. E AVE. TYPE OF STREET Parace
THE PREMISES BEING LOT NO. 10167 , HOUSE NO. 1933
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN OF THE DEPARTMENT OF PUBLIC SERVICE.
Name of Contractor (9 4. Diame)
V

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.