## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7821 AND SIGNED WHEN RETURNED

DATE INSPECTED 7-7-CS	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 183C	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  CURB LINE AND DEPTH
WAS LATERAL AT SURE? VES	NAME OF CONTRACTOR ADIANA
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
1 -	- 30a. 7'o. 4'
	12 49/20
SIGNED POUR INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

## Nº 7821

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

J. (41 6
MASSILLON, OHIO,
$\langle \langle \langle \rangle \rangle \rangle$
RECEIVED OF U.J. Nicesia FEE OF \$50
FOR WHICH/PERMISSION IS GRANTED NOWY W. Crawl
TO TAP Same and SEWER ON THE Case
of Unkeret PE. AVE. TYPE OF STREET as placet
THE PREMISES BEING LOT NO. 11566 HOUSE NO. 1836
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR O. J. Diana

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.