Nº 7829

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-2-65	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED 6 11	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 93 5, 0 5 M 11 D 15 M
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAIN NO	NAME OF CONTRACTOR H. DRBAN
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
and the second of the second o	16
M. J.	——————————————————————————————————————
	4.0 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2
	021
SIGNED R. Latham	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY	

Nº 7829

PERMIT TO TAP SEWER

MASSILLON, OHIO, Clicy. 4
RECEIVED OF MASSILLEN, OHIO, STEE OF \$ 50-
FOR WHICH/PERMISSION IS GRANTED Lilts Ralty
TO TAP SEWER ON THE Cast
OF 13 TKS. W. AVE. ST. TYPE OF STREET DELT
THE PREMISES BEING LOT NO. 2878 , HOUSE NO. 1010
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Harry U. Com
$oldsymbol{\mathcal{U}}$

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.