

Nº 7831

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 8-5-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM.

HOUSE NO. 700

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR H URBAN


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



$K \approx 10$

62

 $\frac{1}{4} \times 8\frac{1}{2} = 0$ 

SIGNED R. Nathan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7831

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Aug. 5
RECEIVED OF Harry Urban FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED Carl Oser
TO TAP Sanitary SEWER ON THE North
OF Sandy St. E. AVE. Oiled
ST. TYPE OF STREET
THE PREMISES BEING LOT NO. 11367 HOUSE NO. 700

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry Urban

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.