Nº 7835

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DE	FIRST MANHOLE DOWN STREAM STUB IN MA 6 D	ED 8-24-	DATE INSPECTED
	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	20 JSED 6"	HOUSE NO.
4	<u> </u>	AT CURB? NO	
James	NAME OF CONTRACTOR D. / FAMILE L	D TO MAIN_ / ES	WAS ATTACHED T
16' = 7'D	OF LATERAL TO WALL OF BUILDING SERVED.		SHOW BY DIAGRA
6	FILED AT ENGINEER'S OFFICE 13-33-65	INSPECTOR FO	SIGNED PO
<u> </u>	OF LATERAL TO WALL OF BUILDING SERVED. 16 7 7 7 7 7 7 7 7 7 7 7 7 7	AT CURB? NO D TO MAIN YES FRAM RELATION OF L	WAS LATERAL AT WAS ATTACHED TO SHOW BY DIAGRA

Nº 7835

OFFICE OF THE DIRECTOR OF PUBLIC SET PERMIT TO TAP SEWER

	MASSILLON, OHIO, Cluy 34
RECEIVED OF Lucias Alco	FEE OF S
A second contract of the second contract of t	Burrorefie
TO TAP SCORE SEV	VER ON THE PART CA
of the see of, W. AVE. TYPE	DE OF STREET Jack
THE PREMISES BEING LOT NO. 3574	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	
NAME OF CONTRACTOR	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.