

✓ 11-

Nº 7849

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

9-15-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

326

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

? OLD HOUSE LATERAL

WAS LATERAL AT CURB?

YES


WAS ATTACHED TO MAIN

NO


NAME OF CONTRACTOR

R. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



L.W.E.



4TH ST

SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-23-65

REMARKS

CLEANED OUT OLD LAT. FROM CURB TO MAIN LINE

Nº 7849

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO

RECEIVED OF

Gardegar Service Store, Inc.

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sanitary

SEWER ON THE

North

OF

L. V. C.

AVE.

ST. TYPE OF STREET

Handcar

THE PREMISES BEING LOT NO.

146

HOUSE NO.

326

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Russell Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.