Nº 7872

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-9-65 IF	SO HOW AND LOCATION FROM	
en e	RST MANHOLE DOWN STREAM	
HOUSE NO. 741		
SIZE OF PIPE USED	STANCE FROM FIRST MANHOLE DWN STREAM TO DITCH AT 250 M. C	5 H 8'D
WAS LATERAL AT GURET YES Pr	- 60 - 2. การ์ได้เมื่อสุดิพาการ การพระการและสาโดยกา	
- WAS ATTACHED TO MAIN N	IAME OF CONTRACTOR	DIANA
SHOW BY DIAGRAM RELATION OF LATERAL		ar!
	in the state of th	1 / 1 7'0
Land and the state of the state	V	* / ·
en kaltine til men til men kenning med som til en	 A set of the second property of	/42
	The second secon	1251/280
YN YN	gi	2501-)
SIGNED INSPECTOR FOR CITY	<u>Űnar den Milo</u> , Filed at éngineér's office That and the state of t	
PFMARKS	and the second of the second o	

Nº 7872

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Becember 9
RECEIVED OF A. Dian	بر سی در
FOR WHICH PERMISSION IS GRANTED Jan	is Path
1 - //	WER ON THE WLAT
of Deerfield 71.6. AVE. TYL	
	, HOUSE NO. 741
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	e No. 2323, duly passed by the City Council, an
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR (1) Drain	<u>d</u>

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.