

✓ 8-

Nº 7886

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-1-66

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1224-26

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


212' S. OF MH 7' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR H. URBAN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED W. HAMMER

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Duplex

Nº 7886

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO

RECEIVED OF

Massillon Cabinet Shop

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

Harry Huber

TO TAP

Sanitary

SEWER ON THE

East

OF

13th St. S.W.

AVE.

ST. TYPE OF STREET

Gravel

THE PREMISES BEING LOT NO.

8888

HOUSE NO.

1224
1226

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry Huber

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.