Nº 7893 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-26-66	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1003		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 25 E, 05 MH 6 0E	TE P
WAS LATERAL AT CURBI	NAME OF CONTRACTOR	<i>t</i> ·
WAS ATTACHED TO MAIN NO	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
	3/2	
	80	
	Service of the servic	//8
N	15	4K
lace de	The second secon	
SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE	25
REMARKS		
A EMACKET		

Nº 7893

PERMIT TO TAP SEWER

MASSILLON, OHIO, April 26
RECEIVED OF Call Hunsinger FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED Harry White
TO TAP Santary SEWER ON THE Sactific
Diministrate AVE. TYPE OF STREET Chip of Street
THE PREMISES BEING LOT NO. 475 8384 HOUSE NO. 1003
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR LANG Achan

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.