

Nº 7912

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED ^{NOT} 12-15-66

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM USED THEIR OWN LAT. JUST

HOUSE NO. 2813

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR R. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature]
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS THESE MEASUREMENTS ARE APPROX. THIS PART INSPECTED
THIS INSP. NOT WORKING THIS SEWER OUT IN ON S.

Nº 7912

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 10

RECEIVED OF

Reece Marks

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

St. Barbara's Church

TO TAP

Sanitary

SEWER ON THE

South

OF

L. W. W. V

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

O. h. 243

HOUSE NO.

2813-L. W. 1

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.