<u>~3</u>

Nº 7919

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| HOUSE NO. 15 | FIRST MANUSCHE DOWN STREAM 259 10 |
|--|---|
| SIZE OF PIPE USED 4" | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? NO STACK WAS ATTACHED TO MAIN | NAME OF CONTRACTOR W. URBAN |
| SHOW BY DIAGRAM RELATION OF LATE | RAL TO WALL OF BUILDING SERVED. |
| | N 254 N |
| | 10° N' = 200' -> 0 |
| SIGNED INSPECTOR FOR CIT | FILED AT ENGINEER'S OFFICE |
| REMARKS | |

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

Nº 7919

| - Ha | massillon, OH | FEE OF \$ |
|--------------------------|----------------------------|------------|
| | I Secret Ation | |
| PHICH PERMISSION IS GRAN | sewer on the | South |
| Lavid 1 | AVE. ST. TYPE OF STREET | Oil healed |
| REMISES BEING LOT NO. | 757-5158 H | JUSE NO |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

NAME OF CONTRACTOR HARY When