Nº 7921

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-15-66	IF SO HOW AND LOCATION FROM	TA 1918.0	At ON Trucks
HOUSE NO. 1875			***************************************
SIZE OF PIPE USED 8" 1 CANTES	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? No			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR		DIANA
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SE	RVED.	
			CAST TROWN
SIGNED TATALON INSPECTOR FOR CITY	FILED AT ENG	GINEER'S OFFICE	10 20 VS (
REMARKS	-		TOUR V SEW FRQ

Nº 7921

PERMIT TO TAP SEWER

ı			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	оню Амд	with 1	9.
	л	MA5 ح	SSILLON, C	Оню. <u>У: У У У</u>	And the state of t	
RECEIVED OF_	a. J.	Diana			FEE O	<u> </u>
FOR WHICH PERMISSION		Perny 1		her Co.		
7	N. Z	7		11	1	
TO TAR Samo	Tary	SEWER C	ON THE	South	£	
<i>A</i> 2	and a	AVE. ST. TYPE OF	-	Chip &	Sect	
	Pt	O.h. 310		7 - 2		- C4*
WORK TO BE DONE IN A	CCORDANCE W	/ITH ORDINANCE No.	. 2323, DI	JLY PASSED BY	THE CITY CO	UNCIL, AN
OF THE DEPARTMENT O						

NAME OF CONTRACTOR II. Wrand

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.