No. 7924 And Signed when returned

DATE INSPECTED 9-6-66	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 9435	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE TO FIRST MAN
WAS LATERAL AT CURB?	and the second of the second o
-WAS ATTACHED TO MAIN	NAME OF CONTRACTOR THOMPSon
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
I SURE ESTATE ESTATE SERVICES	50 60'
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

V

Nº 7924

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, Settember 6 1
Walnut Fabruarde 15
RECEIVED OF THE OF \$
FOR WHICH PERMISSION IS GRANTED
of Laggart St. Type of Street Chip & Scal
I was to see the second of the
THE PREMISES BEING LOT NO. 11 33 1 HOUSE NO. 500 430

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

HAME OF CONTRACTOR COULT Thompson

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.