## THE PROPERTY OF THE FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7983 AND SIGNED WHEN RETURNED

DATE INSPECTED 6-30-67 475	IF SO HOW AND LOCATION FROM MYE 105 11, 0 PM 10 S
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	ini
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A. DIANA
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	1s'
	— N /
ed emiliar businessis edil	e the same of the
	102
•	A/154
6 1 8	105
SIGNED INSPECTOR FOR CIT	
REMARKS	

## Nº 7983

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

4.5	MASSILLON, OHIO, June 27	
- 0	MASSILLON, OHIO,	
RECEIVED OF	read FEE OF \$ 5.	
FOR WHICH PERMISSION IS GRANTED	Villian Benner	
11	SEWER ON THE	
of 20 # St. J. E.	AVE. TYPE OF STREET Chip & Leal	
	593 , HOUSE NO. 275	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.