## No. 7995 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-19-67	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2622.	DISTANCE FROM FIRST MANHOLE:
SIZE OF PIPE USED	CURB LINE AND DEPTH
WAS LATERAL AT CURB?	- 10-1 P
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
The second secon	33
	77/2
re a tarter Sierrich war ein van der eine Germente	8Bmd.
SIGNED ON Kirly	10 19 - 145 - C
INSPECTOR FOR C	TY AT AT A PART OF A PART
REMARKS	

## Nº 7995

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSI	ILLON, OHIO, Charge T	18_1
teale I	7	ILLON, OHIO, Land Market Marke	4
RECEIVED OF	4	FEE C	)F <b>\$</b>
and the state of t	and account and	Carry Store	
FOR WHICH PERMISSION IS GRANTED		· · · · · · · · · · · · · · · · · · ·	
TO TAP Lancing	SEWER ON	THE Store Da	ET
		TREET MARK Duga	
THE PREMISES BEING LOT NO.	174	, HOUSE NO. 2 6 9 12	,
WORK TO BE DONE IN ACCORDANCE WITH CONTINUES OF THE DEPARTMENT OF PUBLIC SERVICE.	ORDINANCE No. 2:	•	
NAME OF CONTRACTOR			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.