REMARKS.

Nº 8008 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED //-8-67	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT SURET VES	
WAS ATTACHED TO MAIN NO	NAME OF CONTRACTOR M. HOLDERBAUM
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.
	N JOBENA 30 BENA
n de 1990 e la constitución de la proposición de la constitución de la constitución de la constitución de la c La constitución de la constitución	The second of the control of the con
994	7.5
SIGNED INSPECTOR FOR CITY	and the control of the

N_{\odot} 8008

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO Ottober 13
	FEE OF \$ 5.
FOR WHICH PERMISSION IS GRANTED AMAM	. andirean
TO TAP Danieland	SEWER ON THE MEET
OF 19 6 1. S. E. AVE.	TYPE OF STREET HIS & LEAD
THE PREMISES BEING LOT NO. 6236	
WORK TO BE DONE IN ACCORDANCE WITH ORDINA OF THE DEPARTMENT OF PUBLIC SERVICE.	NCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR HARMACLERICA	MI)

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.