

✓
No 8022

15:10
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-3-5-68

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 991

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? 8' OFF

1" SOUTH OF DEAD END 7'

WAS ATTACHED TO MAIN OF MAIN

NAME OF CONTRACTOR R MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED S. V. Nathan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS THIS SEWER IS RELIED 50' FROM THE HOUSE OUT
IT HAD 6" FALL THE WRONG WAY

Nº 8022

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, January 2

RECEIVED OF

Roscoe Marks

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

Shuman E. Shert

TO TAP

Sanitary

SEWER ON THE

South

OF

Cherry St. N. W.

AVE.
ST. TYPE OF STREET

Cherry & East

THE PREMISES BEING LOT NO.

9736

HOUSE NO.

991

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Marks

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**