8025

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-25-6	= " " " " " " " " " " " " " " " " " " "	
HOUSE NO. 1299	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 17 E OF MH	/ 7'D.
WAS LATERAL AT CURB? VES	100 350 NAME OF CONTRACTOR 100 TO STATE OF STATE	DIANA
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.	12
ស្ត្រាយនេះស្ត្រាប់ នគរម នគរ ១៩៩១៩៩១៩១៩១ បានប្រាស់ ស្ត្រាយនេះស្ត្រាប់ នគរម នគរ ១៩៩១៩៩១៩១៩១៩១៩១៩១៩១៩១៩១៩១៩១៩១៩១៩១៩១៩១៩	N The second of	52
SIGNED V. V. Matta	FILED AT ENGINEER'S OFFICE	
INSPECTOR FO	ed a liberto, combine i subblind he eller	,

Nº 8025

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON,	OHIO, Feb.	<u>// *** *.</u> .
RECEIVED OF Shirt of The	ance-		ETE OF S
		casin	
Lanctary		West	
of Janin and S. W. AVE. ST. TYP	PE OF STREET.	Chip & S.	ia C
THE PREMISES BEING LOT NO. 90919 90 9 2		HOUSE NO. 119	7.9
	-N- 0000 -		7 Caau

111

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.