## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

AND SIGNED WHEN RETURNED

DATE INSPECTED 8-13-68	IF SO HOW AND LOCATION FROM
HOUSE NO. 73/	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM EIRST MANHOLE COMMON OF THE COMMON OF T
WAS LATERAL AT CURB?	in de la Calabara de la companyo de la companyo de la segui de esta de la companyo del companyo de la companyo
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR FRANKS
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED,
N F	PELAY.
	Bend 3M
SIGNED William Thomas	Alley FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CI	

8067

Nelsy V

8067

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, August	8
RECEIVED OF Richard Flanchs FEE	OF 5 3.
FOR WHICH PERMISSION IS GRANTED Juanilo Daily	
TO TAP Santary SEWER ON THE South	accep.
OF Misle and J. W. AVE. TYPE OF STREET Chip & Le	
THE PREMISES BEING LOT NO. 5735 HOUSE NO. 731	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

IAME OF CONTRACTOR Richard Trans

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.