Nº 8079

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-9-68 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2776
SIZE OF PIPE USED 6" DOWN STREAM TO DITCH AT 8 EAST OF MY 9 DE
WAS LATERAL AT SURBY VES Prop
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR GOOD NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
N 30
The state of the s
084ND 152
30 30
1/201
SIGNED FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE
DEMARKS

## N 9 9

## PERMIT TO TAP SEWER

		Maggi	u au aua	Stendar 17	
THE MOTE TO THE	0 1	O MASSI	LLON, OHIO		—
RECEIVED OF.	Falin	Oaks		FFF OF S	5
		1		?	
FOR WHICH PERMISSION	N IS GRANTED	Ruccell	Back	e/	
7			J.	<i>c</i> ·	
то так важе	lary	SEWER ON	THE 7/0	ceth	
of Stone Ra		AVE. ST. TYPE OF S	TREET Chij	; & Sul	
THE PREMISES BEING L			, HOUSE NO.	2226	
		70			
WORK TO BE DONE IN A	CCORDANCE WITH	ORDINANCE NO. 2	323, DULY PASSEI	BY THE CITY COUNCIL,	, AN
OF THE DEPARTMENT O	F PUBLIC SERVICE	<u>.</u>		2 de	
NAME OF CONTRACTOR	Och	0			
		•			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.