Nº 8104 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-7-69	IF SO HOW AND LOCATION FROM 87-2129 E	, 05 M
HOUSE NO. 2037		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT GURB LINE AND DEPTH	
WAS LATERAL AT CURB? 15		•
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR M. HOLDE	RBAUM
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
Taking the second secon	13 15	es ***
	10 50 H	
ing purity from the second second	3º 75. 7D 12	·
	-/ [4]	(3)
N	1,19	- 8 ⁵ - 3
SIGNED Vi Vallas	FILED AT ENGINEER'S OFFICE	
INSPECTOR FOR CIT	Natural services in the service of the services	I

REMARKS _

PNO.

office of the director of public seingly PERMIT TO TAP SEWER

CUNITS

MASSILLON, OHIO, LAMMANY S. S. G.

FOR WHICH PERMISSION IS GRANTED M. Sewer on the South

TO TABLE AND SEWER ON THE SOUTH

OF MANAGEMENT SEWER ON THE SOUTH

THE PREMISES BEING LOT NO. 6.110-6.111-6.212 HOUSE NO. 2037

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Haldesbaum

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.