FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED AND SIGNED WHEN RETURNED

DATE INSPECTED 4-15-69	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 818	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 134 10 DEEP CURB LINE AND DEPTH 134
WAS LATERAL AT CURB? YES	and the angle of the second of
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
ا المنظم الم المنظم المنظم المنظ	7'D +2'- N
in which is the many waters to all the property	10.00
	P. 12
Dage	13.4
SIGNED CONTRACTO	FILED AT ENGINEER'S OFFICE
V INSPECTOR FOR CIT	
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SEI

N 8112

PERMIT TO TAP SEWER

	MASSILLON, OHIO, March 26
RECEIVED OF WM Thick	FFF OF S 5. 4
FOR WHICH PERMISSION IS GRANTED Lave	Hathaway
Sanctary	Fact
Ochcust Lane, 7.6. AVE. TY	PE OF STREET GLANCE
THE PREMISES BEING LOT NO. 12520	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC OF THE DEPARTMENT OF PUBLIC SERVICE.	E No. 2323, DULY PASSED BY THE CITY COUNCIL, ANI

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.