

Nº 8121

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-14-69

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 815 L.W.W


SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No Repair

WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR M. HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Kelley

Nº 8121

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO *April 10*

RECEIVED OF *Halderbaum* FEE OF \$ *5.*

FOR WHICH PERMISSION IS GRANTED *Mr. Piefer*

TO TAP *Sanitary* SEWER ON THE *North*

OF *Main Ave.* AVE. TYPE OF STREET *Hard Surface*

THE PREMISES BEING LOT NO. *9858* HOUSE NO. *815 - H. W. W.*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Halderbaum*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**