


Nº 8151

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-5-69IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMRelayHOUSE NO. 1626DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHSIZE OF PIPE USED 6"WAS LATERAL AT CURB? NOWAS ATTACHED TO MAIN NONAME OF CONTRACTOR M. HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

L. Satham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Relay
Nº 8151

OFFICE OF THE DIRECTOR OF PUBLIC SEWER
PERMIT TO TAP SEWER

May 23, 1969

Mike Maylar

100 S.E.

Dirt

at North

738

1626

Haldubaum

5.00

W. Kracker

MASSILLON, OHIO

July 23

RECEIVED OF

Haldubaum

FEE OF \$ *5.*

FOR WHICH PERMISSION IS GRANTED

Young (Mike Maylar)

TO TAP

Sanitary

SEWER ON THE

North

OF

Ute Ave. S.E.

AVE.
ST. TYPE OF STREET

Dirt

THE PREMISES BEING LOT NO.

12738

HOUSE NO.

1626

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Haldubaum

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.