Nº 8153

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 8-5-69 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|---------------------------------------|---|
| HOUSE NO. 223C | |
| SIZE OF PIPE USED (1) | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH LEAST OF PRAD LINE CURB LINE AND DEPTH |
| WAS LATERAL AT GURB? | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR GERTSEN SLAGE |
| SHOW BY DIAGRAM RELATION OF LATE | RAL TO WALL OF BUILDING SERVED. |
| | |
| · · · · · · · · · · · · · · · · · · · | 30°3 50' K 45°13. |
| | 10 190 |
| SIGNED UNSPECTOR FOR CIT | FILED AT ENGINEER'S OFFICE |
| REMARKS | · · · · · · · · · · · · · · · · · · · |

Nº 8153

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| MASSILLON, OHIO, aug. 4 |
|--|
| RECEIVED OF Lewels lague FEE OF & 5. |
| FOR WHICH PERMISSION IS GRANTED DON Mª Fances |
| TO TAP Sasitary SEWER ON THE Marth |
| OF Stane Rd. N. E. AVE. ST. TYPE OF STREET Chip & Seel |
| THE PREMISES BEING LOT NO. 12515 HOUSE NO. 2236 |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PABSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE. |
| O. A. A. |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.