8231

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-18-7	O IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 745	— District France Control of the Con
SIZE OF PIPE USED 4"1	DISTANCE FROM FIRST MANHOLE OF CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	and the second of the second o
WAS ATTACHED TO MAIN NO	NAME OF CONTRACTOR M. HOLDYERBAUM
	TERAL TO WALL OF BUILDING SERVED.
	2,40 → 1€15
SIGNED INSPECTOR FOR	CITY FILED AT ENGINEER'S OFFICE

Klay

PERMIT TO TAP SEWER

	MASSILLON, OHIO 7/23/
RECEIVED OF Haldubaces	FEE OF \$ 5, 1
FOR WHICH PERMISSION IS GRANTED	Blanchard
TO TAP Sanctary SET	WER ON THE WEST
7 - 10 - 10 0 · AVE.	PE OF STREET Hard Lufae
THE PREMISES BEING LOT NO. 1073	, HOUSE NO

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Holdichaceur

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.