

Repaired Stack

2-

Nº 8247

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-9-70

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

WYE 22' S. OF MH 16

HOUSE NO. 325

SIZE OF PIPE USED 4"



DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R. FRANKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

4" STACK USED BENDS OFF OF STACK, OLD L.I.
HAD STRAIGHT PIPE CUT TO FORM BENDS

Kelay

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

Nº 8247

MASSILLON, OHIO, *Sept 8*

RECEIVED OF

Richard Franke

FEE OF \$ *5.*

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sanitary

SEWER ON THE

West

OF

6th St. S.W.

AVE.

ST. TYPE OF STREET

Brick Base Blk

THE PREMISES BEING LOT NO.

9360

HOUSE NO.

325

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Richard Franke

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.