*	
829	6

## $N^{\circ}$ Following data to be answered by inspector and signed when returned

DATE INSPECTED 6-3-7/ IF SO HOW AND LOCATION FROM STUB IN MA 8 DD
HOUSE NO
SIZE OF PIPE USED 6 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR L. SCHUMACHEY
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
and the second of the second o
and the second of the second o
I Vatheren
SIGNED FILED AT ENGINEER'S OFFICE INSPECTOR FOR CITY
PEMARKS

## N? 8296

## PERMIT TO TAP SEWER

about 19
MASSILLON, OHIO, April 19
Schumacher Couch. Co. 5.
RECEIVED OF CAUMACAU CRUEN. CO. FEE OF \$ 3.
Anited Steel Workers of Crained # 112
FOR WHICH PERMISSION IS GRANTED
TO TAP Sancting SEWER ON THE West
TO TAP SEWER ON THE
of_ 9th S. W. AVE. TYPE OF STREET Chip of Scale
THE PREMISES BEING LOT NO. 11 11 11 11 11 11 11 11 11 11 11 11 11
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
of the Department of Public Service.
NAME OF CONTRACTOR SCHEMACKER

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.