FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 8324 AND SIGNED WHEN RETURNED

HOUSE NO. 439 SIZE OF PIPE USED WAS LATERAL AT GURB? YES WAS ATTACHED TO MAIN NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH NAME OF CONTRACTOR TO STREAM TO DITCH AT CURB LINE AND DEPTH NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATER	NAL TO WALL OF BUILDING SERVED. 15 70000 ST
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE

Nº 8324

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO,	May 28.
Earl & lick	
RECEIVED OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	
TO TAP Sandam SEWER ON THE U	lest
28 th how AVE. TYPE OF STREET	hip y Seal
THE PREMISES BEING LOT NO. 12142 HOUSE	NO. 439
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PA	ssed by the City Council, and
of the Department of Public Service.	
NAME OF CONTRACTOR	 .

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.