REMARKS \_

## Nº 8359 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED AND SIGNED WHEN RETURNED

DATE INSPECTED 8-24-7	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	Hospit 3
HOUSE NO. 308		7
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR F. STE	IN BACH
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	1
	and the state of t	12 12
en e		- nh
N = 1	• Carlos de Carl	! /50
	<del>}</del>	118
DID.	/5'8'	13'0 PP
SIGNED	EN ED-AT ENGINEER'S OFFICE	
INSPECTOR FOR C		

## N? 8359

## PERMIT TO TAP SEWER

, MASSILLON, OHIO, AUG. 31
RECEIVED OF VESSIE CECIL FEE OF \$25
FOR WHICH PERMISSION IS GRANTED STEINBACH EXCRUATING
TO TAP SEWER ON THE FORTH
OF 22 (V) ST N.CO. AVE. TYPE OF STREET CHIP & SCAL
THE PREMISES BEING LOT NO. 7243 HOUSE NO. 308
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.