

9.

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

✓
Nº 8361

DATE INSPECTED 9-2-71

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 284-286

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____



67' UP STREAM AT 8' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN -

NAME OF CONTRACTOR Howlett

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 8361

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Sept. 1
RECEIVED OF McDonald FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary SEWER ON THE East
OF 24TH ST. S.E. AVE. Chip & Seal
ST. TYPE OF STREET
THE PREMISES BEING LOT NO. 13457 HOUSE NO. 284, 286

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Howbett

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.