Nº 8370

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 847		· ·
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT GURBI YES	en e	
WAS ATTACHED TO MAIN_ NO	NAME OF CONTRACTOR	MALAUITY
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	5 Krip
	(a) Single Property of the Control of the Contr	
		36 X4!
•		
SIGNED 1	FILED AT ÉNGINEER'S OFFICE	Ò-
INSPECTOR FOR C		
REMARKS		

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

 $\mathbf{N}^{ ext{o}}$ 8370

MASSILLON, OHIO SEPT 21	•
R. Ft. Kanne	,
Harr Alut	
FOR WHICH PERMISSION IS GRANTED	-
TO TAP SEWER ON THE COURT	-
of langleward AVE. TYPE OF STREET Chip & Jea	4
THE PREMISES BEING LOT NO. 13016 HOUSE NO. 1842	-

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR TWO malavete

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.