Nº 8380

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED _//-/6-7/	IF SO HOW AND LOCATION FROM	
HOUSE NO. 2141	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED 6 11	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH S4	
WAS LATERAL AT CURB7_		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A. GLICK	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
.		
	60°	
4	1.78DF	
V		
. O. Ow		
SIGNED THE	FILED AT ENGINEER'S OFFICE	
NSPECTOR FOR CIT	F54:	
REMARKS		

N? 8380

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

institution of the second of t	MASSILLON, OHIO, Honombur 8
.w/	MASSILLON, OHIO, Hamilun 8 1
RECEIVED OF Lack Mich	FEE OF 5
FOR WHICH PERMISSION IS GRANTED PARKE U	Phillips
<u> </u>	
TO TAP & andary	WER ON THE
of Margelet Mr. AV. AVE. ST. TY	
13077	HOUSE NO. 2/4/
THE PREMISES BEING LOT NO.	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	EE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR Albert Land	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.