

5:52
✓

Nº 8393

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-9-71

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 39

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Beovel Exccy.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.


V. Vatham
INSPECTOR FOR CITY



SIGNED _____
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Cut-off

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

Nº 8393

MASSILLON, OHIO, *November 23*

RECEIVED OF *Beann Excavating Co.* FEE OF \$ *05.*

FOR WHICH PERMISSION IS GRANTED *Beann Excavating Co.* *Special License*

Cut-off TO TAP *Sanitary* SEWER ON THE *South*

OF *Warwick Ave. W. W.* AVE. ST. TYPE OF STREET *Chip & Seal*

THE PREMISES BEING LOT NO. *3540* HOUSE NO. *39*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Beann*

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.