FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-1-72	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6" WAS LATERAL AT CORRES? V=5	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 271 west of M 5000
WAS ATTACHED TO MAIN FOR SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	NAME OF CONTRACTOR 90 H A Colubration 1 21' 1900
	2. 16, 12,00 10, 12,00
	P 8 2 2 1
SIGNED W. HAMBER Inspector for City	FILED AT ENGINEER'S OFFICE

№ 8428

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

MASSILLON, OHIO, Lee. 2
RECEIVED OF 14.4 11. Continues FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED About 6. Millia
TO TAP Sanitary SEWER ON THE SLUTTE
of Carline Otic S. V. AVE. TYPE OF STREET Chips & Lea
THE PREMISES BEING LOT NO. 12382 , House No. 2031
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. 47. M. HOLDERBAUN

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.