№ 8472

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-26-77	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		411
HOUSE NO	DISTANCE FROM FIRST MANHOLE	FAST OF MY	
SIZE OF PIPE USED6	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			. <i>4</i>
WAS ATTACHED TO MAIN		R. Franks	R \$
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.		
N-7		0-100	
		\$ 7 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	νP
	•	0 1 2	/ ",
	26T#5T -	200	
SIGNED Inspector for City	FILED AT ENGINEE	ER'S OFFICE	
		*	
REMARKS			

√º 8472

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

м	ASSILLON, OHIO, 1-12
RECEIVED OF Hornes of Fralit	core FEE OF \$ 25.
FOR WHICH PERMISSION IS GRANTED HAMES	of Ladition
TO TAP Sanctary SEWEF	
OF 16 4 11.11. AVE. TYPE	OF STREET Chip of les
THE PREMISES BEING LOT NO. 1316 9	1
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 1	
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR THANKS	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.