## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN-RETURNED

DATE INSPECTED 5-1-72	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 325	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  TOURD 173 Last of MH 6/
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR PARKS
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	14 D
$\mathcal{V}$	3080
SIGNED V. Jathan	FILED AT ENGINEER'S OFFICE
Inspector for City	
And the second second	E178-
REMARKS	

## **№** 8489

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	apid	27
RECEIVED OF Macae	Marks	<u> </u>	. FEE OF \$ 2.5
FOR WHICH PERMISSION IS GRANTED 7.007	Cumply .	of Gar	<u> </u>
TO TAP Sanitary		7	
of Take One 516. A			<u> </u>
The premises being lot no. $962$	, HOUSE,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	/ <sub>No.</sub> 32	5
WORK TO BE DONE IN ACCORDANCE WITH ORDINAN			
OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR 21/aids			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.