## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

8501

DATE INSPECTED 5-30-	22 IF SO HOW AND LOCATION FROM	•	
	FIRST MANHOLE DOWN STREAM		
HOUSE NO. 894			
	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	E	
SIZE OF PIPE USED	CURB LINE AND DEPTH		
WAS LATERAL AT SURBY YES			
WAS ATTACHED TO MAIN 20	NAME OF CONTRACTOR	M. HOLDERBAL	m
SHOW BY DIAGRAM RELATION OF LATERA			
		8'	
·		TE 7's	ip. /// n c
N	NAME:	STUPE	4" PIF
er de la companya de La companya de la co		130 /30	4e
2			- WY NET.
		F	
·			510.
SIGNED WH HAMMER		6'berio	
SIGNED Inspector	r for City	T ENGINEER'S OFFICE	
PEDAIR			
11 F 11 2 2 2 2			

Nº 8501

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, 21/ay 26
RECEIVED OF Haldubaum FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED GRANTED PLANAE PLICE
TO TAP Sautand SEWER ON THE Gast
OF 1st 11 M. 6 ST. TYPE OF STREET Hand lungare
THE PREMISES BEING LOT NO. 9693, HOUSE NO. 894
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR AND

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.