FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-5-77 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 820 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH. 200 // North of My Prop.
WAS LATERAL AT BURB? WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
750.
QQ 14 + 200' -
SIGNED FILED AT ENGINEER'S OFFICE Inspector for City REMARKS

№ 8502

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSI	LLON, OHIO, Jun	<u>e</u> 5
RECEIVED OF Paul	Konon	vaku	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Paul	Konto	Au
South	1 el	THE ENST	- 0
1 . 0	AVE.	Ch	py See
of Jangewood	AVE. ST. TYPE OF S	TREET.	700
THE PREMISES BEING LOT NO. 150	/ / Share	, HOUSE NO	320

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR TILLS Malavite

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.