## $^{1}$ Following data to be answered by inspector $^{1}$ 8503 $^{2}$ and signed when returned

DATE INSPECTED 6-15-22 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM.
HOUSE NO. 326  DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT
WAS LATERAL ALBURB?
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR CYCETEXCA
SHOW BY DIAGRAM RELATION OF LATERAL-TO WALL OF BUILDING SERVED.
No Marie Co
202
SIGNED FILED AT ENGINEER'S OFFICE
REMARKS

Nº 8503

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, Jene 6
RECEIVED OF Crest E franching	7 FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED Williams	
TO TAP Sanctary SEV	<i>*</i>
OF Law Unio. N. 6. AVE. TY	•
THE PREMISES BEING LOT NO. 13548	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	·

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.