

N^o 8511

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-20-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 843

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? ~~NO~~ YES

PROP

24' EAST 5' MT ON:
7' DEEP

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

IP. FRANKS


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED

S. S. S. S.
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS



Nº 8511

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

June 20

RECEIVED OF

M^cFarren Bldg.

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

George Campanelli

TO TAP

Sanitary

SEWER ON THE

West

OF

Tangwood Dr. W.E.

AVE.

ST. TYPE OF STREET

Chip & Seal

THE PREMISES BEING LOT NO.

13019

, HOUSE NO.

843

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Franks

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**