

N^o 8520

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED

8-1-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Tapped MH

HOUSE NO.

1875

SIZE OF PIPE USED

6" C.I.P.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

NO

WAS ATTACHED TO MAIN



yes

NAME OF CONTRACTOR

J. Wisler

G. DIANA INC.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Industrial

No 8520

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

July 21

RECEIVED OF

Perry Rubber Co

FEE OF \$

56

FOR WHICH PERMISSION IS GRANTED

Perry Rubber Co

TO TAP

Sanitary

SEWER ON THE

Sanitary

OF

Frank Ave. S.E.

AVE.

ST. TYPE OF STREET

Chap & Seal

THE PREMISES BEING LOT NO.

Sub. 310 40 1.455

HOUSE NO.

1875

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

J. J. Diana

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.