✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-21-72 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM LLYE 107 Least of MI
HOUSE NO. 2036 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH.
WAS LATERAL AT CURB? NO
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
1 4 pc c.o.
Cl'
107' 3'
SIGNED FILED AT ENGINEER'S OFFICE Inspector for City

№ 8535

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSI	LLON, OHIO, August 21
RECEIVED OF 14. of 7/2 Centrate	FEE OF \$
FOR WHICH PERMISSION IS GRANTED Plantes 711-	Plus
TO TAP Sandary SEWER ON	THE MARKA
of Cala 15. AVE. TYPE OF S	
THE PREMISES BEING LOT NO. 6636401.6635474.0	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-19 OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR /4.8)	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.