$N^{\underline{o}}$ = 8539 Following data to be answered by inspector and signed when returned

DATE INSPECTED $8-29-72$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 336 SIZE OF PIPE USED WAS LATERAL AT CURE?	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT OURS LINE AND DEPTH OF OF OF OF OF OF OF OF OF O
WAS ATTACHED TO MAIN NO LATERAL TO WAL	NAME OF CONTRACTOR
· · · · · · · · · · · · · · · · · · ·	18' Tr'0P
	20 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	5/29DP
SIGNED Jackson for City	FILED AT ENGINEER'S OFFICE
Inspector for City	

№ 8539

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, Chiquist 30,	
RECEIVED OF A.T. DIANA	FEE OF \$ _2_	
FOR WHICH PERMISSION IS GRANTED		
TO TAP 19 11 11 11 11 11 11 11 11 11 11 11 11	NER ON THE X/CRTH	
OF LOR! NE AVE. TY	PE OF STREET CHIPT SEAL	
THE PREMISES BEING LOT NO. 12549	, HOUSE NO. 33 (
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND FOR THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR	9104	
•		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.