

✓
N^o 8546

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

12-20-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

611

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN


NAME OF CONTRACTOR

BEAVER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SAN SEWER
CUT OFF

CUT OFF



SIGNED

William J. Harmon

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

CUT-OFF

Nº 8546

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *September 25*

RECEIVED OF *Beane Clearing*

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *James & Emma Williams*

CUT-OFF

TO-TAP *Sanitary*

SEWER ON THE *West*

OF *4th St. N.W.*

AVE.

ST. TYPE OF STREET *Chippewa*

THE PREMISES BEING LOT NO. *2968*

HOUSE NO. *655*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Beane*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**