

N^o 8581

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-28-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

STURB IN MH 5' D₇₀

HOUSE NO. 1232-34-36-38

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

NO



WAS ATTACHED TO MAIN

YES

NAME OF CONTRACTOR

D. Rogers

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

V. Vathman
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

4 Units
N^o 8581

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/9

RECEIVED OF

Regas & Sons

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Indian North S. 7th N. 1st

TO TAP

Sanitary

SEWER ON THE

East

OF

16th St. S.E.

AVE.

ST. TYPE OF STREET

Chap. & 1st
B-3

THE PREMISES BEING LOT NO.

O.S. 385

HOUSE NO.

1333-1334-1336-12

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Regas

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.