№ 8592

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-6-7 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM.
HOUSE NO. 1526 DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED CE DOWN STREAM TO DITCH AT 25 South of 1/2
WAS LATERAL AT GURET YES Prop.
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
$\frac{1}{h}$
5/ 79/
$\frac{1}{2}$
SIGNED FILED AT ENGINEER'S OFFICE
Inspector for City
REMARKS

№ 8592

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

M	ASSILLON, OHIO, ACC	3
RECEIVED OF RECEIVED OF	ks	FEE OF \$
FOR WHICH PERMISSION IS GRANTED		
TO TAP 5 4 11 17 4 8 4 SEWER	ON THE <u>E 457</u>	
OF MERINA CIRCLE NAVE. TYPE		
THE PREMISES BEING LOT NO. 12568	, HOUSE NO	26
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 1	19-1971 DULY PASSED BY THE CIT	Y COUNCIL, AND 1
OF THE DEPARTMENT OF PUBLIC SERVICE.	4	
NAME OF CONTRACTOR RIGHT	2ks	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.