

11-30

N^o 8596 ✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED

11-14-72

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

IN MH at SIDEWALK

HOUSE NO.

519

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

Yes


WAS ATTACHED TO MAIN

No

NAME OF CONTRACTOR

R. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

V. L. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

1-TOILET 1-URNIAL

Nº 8596

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

Car wash

MASSILLON, OHIO, March 14

RECEIVED OF Reese Marks FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED Erie Oil Co.

TO TAP Sanitary SEWER ON THE 1st

OF S.W. 1st AVE. TYPE OF STREET N. 1st

THE PREMISES BEING LOT NO. 436, HOUSE NO. 519

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND IN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.