FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-15-73	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	NAME OF CONTRACTOR L OF BUILDING SERVED. A ROUND THIS BASEMENT
AND DID N	OT SIND SAN SEWEY

SIGNED	Insp	ector for City		FILED A	AT ENGINEER'S	OFFICE	* THE
DEMARKS			T		12.	*	

ict of

№ 8613

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, Jan.	14
RECEIVED OF Carl Oser	<u> </u>	FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED CALL		
OTAP Sanitary SEN	WER ON THE 6 ast	
of Gulble II S. G. ST. TY		
THE PREMISES BEING LOT NO. 1961		
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR & Liek		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.