

N^o 8618

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-11-73

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM Installed wye 24' EAST

HOUSE NO. 819

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

Dead end
3' deep


WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

V. Latham

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Asphalt to storm sewer

N^o 8618

OFFICE OF THE DIRECTOR OF PUBLIC SEWER
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Feb. 8*

RECEIVED OF *Holdenbaum* FEE OF \$ *2.*

FOR WHICH PERMISSION IS GRANTED *Mary E. Barclay*

TO TAP *Sanitary* SEWER ON THE *South*

OF *Dwight St. N.W. 11-E. AVE.* ST. TYPE OF STREET *Chip & Seal*

THE PREMISES BEING LOT NO. *7555*, HOUSE NO. *819*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Holdenbaum*

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.